

Calibrate Instruments Per National Aerospace Standard:

ANSI Z540-3 OR ISO/IEC 17025:2017

QA REQUIREMENTS:

The supplier shall establish and maintain documented procedures to control, calibrate and maintain all measuring and test equipment that can affect product quality, including test software and personally owned equipment including sci supplied equipment.

1. Calibration shall be tracable to internationally or nationally recognized standards
2. Equipment shall be identified with calibration labels and certification records of the calibration and the calibrating findings test data must be sent to the buyer
3. The calibration interval is understood to be annual unless otherwise specified on the individualline section for each item

Process parts per above instructions and if specific tolerances are required they will be listed in the comments section of each purchase order. If specified standards are not obtainable, contact the calibration coordinator immediately. Time is of the essence in completing this purchase order and it is agreed that the supplier will deliver per the date stated herein. If the supplier is unable to meet the delivery date, supplier must notify the buyer immediately.